

The operating instruction of turbine flow meter

The operating instruction of turbinefow meterThis product uses electronic display system, according to the principle of turbine metering, with complete energy, easyoperation and other characteristics. It can be widely used inpetroleum, chemical, pharmaceutical, transportation, food, trade and other industries.

A. Technical parameters

L .	. reennicar parameters					
	Medium	Diesel oil, urea, kerosene, chemicals, gasoline				
	Import and export	1 " 1.5 " 2"				
	Measurement accuracy	±1%				
	Repeatability	土0.5%				
	Maximum working pressure	20BAR				
	Working voltage	2.3-3.3V				
	Standby time	2year				
	Flow range	10-90L/min, 25-150L/min, 25-200L/min				
	Single count	0.00-9999.9				
	Total accumulation	0-999999				
	Class accumulation	0-999999				
	Unit of measurement	L, GAL, PTS, QTS				
	Single measurement clearing	DISPLAY				
	bingic measurement creating	DIGIDIII				

C. Key notes

CALIBRATE keys: flow rate and shift display switch, measurement calibration, setting coefficients, units; DISPLAY key: clear single count, classcumulative count total cumulative count

D. Operation instructions

a)Clear single count

in the absence of pulse input, press the "DISPLAY" key, then LCD full screen display(as shown below), release the "DISPLAY" keyand return to the standby interface, and thesingle count has been cleared.

B	8.8.8.8 Pts G.
Cal	888888.8 TOTAL X100

b) Class Accumulation Clearance

Without pulse input, long press the "DISPLAY" key(greater than 3 seconds) to display theworkload (as shown below) and short pressthe "DISPLAY" key. At this time, the cumulativevalue of the workload flickers, and then shortpress the "DISPLAY" key again. LCD fullscreen display returns to standby display after1 second, and the cumulative number ofworkloads has been cleared.



c) View the total cumulative sum error coefficient and clear the total accumulation

Check the total accumulation: when there is no pulse input, press the "DISPLAY" key at the same timeAnd "CALIBRATE" key to display the cumulative sum error coefficient (as shown in the figure below)


second, and return to the standby display.

Clear the total accumulation: unscrew the four screws on the plastic transparent cover to take out the battery, press and hold the "display" key and "CALIBRATE" key at the same time, and then replace the battery.




E. Maintenance

B. External description



d)Display switching between flow rate andshift load When counting or standby status, pressthe "CALIBRATE" key to switch the display of flowate and total cumulative (as shownbelow)



e)Parameters settings


Without impulse input, long press "CALIBRATE" keymore than 3 seconds) to switch to coefficientsetting interface (as shown below) Bit flickercan be set, short press "DISPLAY" key tomodify the flicker bit value, short press "CALIBRATE" key to switch flicker bit, long press "CALIBRATE" keyafter setting or wait 15 seconds to exitcoefficient setting and save setting. Set value



parameters	display	real flo	w	
0.990		101L	slow	
1.000	100L	100L	normal	
1.01		99L	fast	
the smaller the parameters are the more slower they are.				

f) Unit settings

In the coefficient setting interface, press "CALIBRATE" to switch to unit flicker, then press "DISPLAY" to switch units (as shown below) press "CALIBRATE" or wait 15 seconds to exit the coefficient setting and save the setting.



When the battery voltage is too low, a battery signappears on the LCD display screen to remind usersof the need to replace the battery Short battery lifecan cause damage to the flowmeter due to leakageof battery during operation. But it is recommended that customers change batteries once a year. It is recommended that customers check the battery electrodes once a year, and remove the corrosion intime. Batteries should be removed if no flow timing is used for a long time.

www.sintek-ia.com